

BETTER BIOMASS SUMMARY AUDIT REPORT

CERTIFICATE HOLDER

Certificate number	2232720
Organization	Rendac Son B.V.
Address	Kanaaldijk Noord 20 5691 NM Son
Country	The Netherlands
Geographical co-ordinates	51° 30' 16.8"N 05° 26' 44.3"E
Website	www.rendac.nl
Version NTA 8080	NTA 8080-1:2015 and NTA 8080-2:2015
Version Better Biomass scheme	NCS 8080:2018-08
Version Interpretation document	Interpretation document N° 8 (2022-01-27)
Date of issue initial certificate	2019-04-05
Date of upgrade to new version	2019-04-05
Date of expiry certificate	2029-04-05

SCOPE OF CERTIFICATION

Type of scope(s)	Producer (collector non-primary residual flows) / Processor
Assessed in framework of Directive (EU) 2018/2001 [RED-II]	YES
Assessed in framework of 'Regulation solid biomass'¹ [SDE]	YES
Production process(es)	The processing of offal (category 1) for the production of meat-and-bone meal
Products	Meat-and-bone meal
Nature of raw materials	Offal (category 1) [586]
Non-modification declaration (only for biomass residual flows)	The organization has not modified its production process(es) to produce more residual flows
Total area of cultivation (only for biomass producer/smallholder)	N/A
Chain-of-custody model	Mass balance

¹ It concerns the Dutch Regulation conformity assessment of solid biomass for energy applications (i.e. "Regeling conformiteitsbeoordeling vaste biomassa voor energietoepassingen") including the legal definition for 'protected species'.

BETTER BIOMASS SUMMARY AUDIT REPORT

Group certification NO
Multiple production locations NO

OVERVIEW PRODUCTION LOCATIONS (in addition to location of certificate holder)

N°	Name of production location	Address	Geographical co-ordinates
NA	NA	NA	NA

CERTIFICATION BODY

Organization DEKRA Certification B.V.
Country The Netherlands
Website www.dekra.com