

# BETTER BIOMASS SUMMARY AUDIT REPORT

## CERTIFICATE HOLDER

<b>Certificate number</b>	2247042
<b>Organization</b>	Van Stipdonk Landschapsinrichting B.V.
<b>Address</b>	Hulsterweg 11 5662TL Geldrop
<b>Country</b>	The Netherlands
<b>Geographical co-ordinates</b>	51° 25' 31.98" N 05° 32' 44.23" E
<b>Website</b>	www.vanstipdonk.nl
<b>Version NTA 8080</b>	NTA 8080-1:2015 and NTA 8080-2:2015
<b>Version Better Biomass scheme</b>	NCS 8080:2018-08
<b>Version Interpretation document</b>	Interpretation document N° 8 (2022-01-27)
<b>Date of issue initial certificate</b>	2020-09-22
<b>Date of expiry certificate</b>	2026-05-2021

## SCOPE OF CERTIFICATION

<b>Type of scope(s)</b>	Producer (collector primary residual flows) / Producer (collector non-primary residual flows) / Processor
<b>Assessed in framework of Directive (EU) 2018/2001 [RED-II]</b>	YES
<b>Assessed in framework of 'Regulation solid biomass' <sup>1</sup> [SDE]</b>	YES (only regarding raw materials *)
<b>Production process(es)</b>	The collection and treatment of woody residues
<b>Products</b>	Wood chips
<b>Nature of raw materials</b>	127 branches and tops hardwood 128 stumps hardwood 129 thinnings hardwood 136 branches and tops softwood 137 stumps softwood 138 thinnings softwood

<sup>1</sup> It concerns the Dutch Regulation conformity assessment of solid biomass for energy applications (i.e. "Regeling conformiteitsbeoordeling vaste biomassa voor energietoepassingen") including the legal definition for 'protected species'.

# BETTER BIOMASS SUMMARY AUDIT REPORT

114 round timber (from nature and landscape management) \*)  
117 stumps (from nature and landscape management) \*)  
118 branches and tops (from nature and landscape management) \*)  
119 other fresh wood (left overs) \*)

**Non-modification declaration**  
(only for biomass residual flows)

The organization has not modified its production process(es) to produce more residual flows

**Total area of cultivation** (only for biomass producer/smallholder)

N/A Ha

**Chain-of-custody model**

Mass balance

**Group certification**

NO

**Multiple production locations**

NO (1 location)

## OVERVIEW PRODUCTION LOCATIONS (in addition to location of certificate holders)

N°	Name of production location	Address	Geographical co-ordinates
1	Biomassacentrum Geldrop Bedrijventerrein De Spaarpot	Spaarpot 139, 5667KV, Geldrop	51° 26' 05.64" N 05° 33' 33.37" E

## CERTIFICATION BODY

<b>Organization</b>	DEKRA Certification B.V.
<b>Country</b>	The Netherlands
<b>Website</b>	<a href="http://www.dekra.com">www.dekra.com</a>