

BETTER BIOMASS SUMMARY AUDIT REPORT

CERTIFICATE HOLDER

Certificate number	2296083
Organization	Ecoson Burgum B.V.
Address	Damsingel 27 9262 NB Sumar
Country	The Netherlands
Geographical co-ordinates	51° 30' 16.8"N 05° 99' 47. 1"E
Website	www.darlingii.com
Version NTA 8080	NTA 8080-1:2015 and NTA 8080-2:2015
Version Better Biomass scheme	NCS 8080:2018-08
Version Interpretation document	Interpretation document N° 8 (2022-01-27)
Date of issue initial certificate	19 juni 2025
Date of upgrade to new version	N/A
Date of expiry certificate	21 mei 2026

SCOPE OF CERTIFICATION

Type of scope(s)	Producer
Assessed in framework of Directive (EU) 2018/2001 [RED-II]	YES
Assessed in framework of 'Regulation solid biomass' ¹ [SDE]	NO
Production process(es)	The processing of offal (Rendering plants)
Products	Diermeel
Nature of raw materials	Diermeel [585]
Non-modification declaration (only for biomass residual flows)	The organization has not modified its production process(es) to produce more residual flows
Total area of cultivation (only for biomass producer/smallholder)	N/A
Chain-of-custody model	Mass balance

¹ It concerns the Dutch Regulation conformity assessment of solid biomass for energy applications (i.e. "Regeling conformiteitsbeoordeling vaste biomassa voor energietoepassingen") including the legal definition for 'protected species'.

BETTER BIOMASS SUMMARY AUDIT REPORT

Group certification NO

Multiple production locations Yes

OVERVIEW PRODUCTION LOCATIONS (in addition to location of certificate holder)

N°	Name of production location	Address	Geographical co-ordinates
1.	Ecoson Burgum B.V.	Damsingel 30 9262 NC Sumar	N 53.181784 E 5.993786

CERTIFICATION BODY

Organization DEKRA Certification B.V.

Country The Netherlands

Website www.dekra.com